

## MAINTENANCE / AFTERCARE OF YOUR WORKTOPS

---

Please remember that wood is a natural material and an appropriate on going regime of oil treatment is essential to maintain the factory pre finished surface protection against stains and humidity, which will ensure a long and trouble free life.

If you need to restore the sheen of the tops in the future when you feel they start to look a little dull, or for precaution every 6 months, a further coat of mineral oil will return them to their natural beauty. The surfaces can be cleaned with damp cloth containing a small amount of mild dishwashing soap.

Keep all oils out of reach of Children Ensure good ventilation within the room when applying oils.